

General Environmental Incident Summary

Incident: 3539 **Date/Time Notice:** 11/7/2014 0947 **DEM Incident No:**
Responsible Party: TPG
Date Incident: 11/7/2014 **Time Incident:** **Duration:** 1 minutes
County: McKenzie **Twp:** 152 **Rng:** 101 **Sec:** 18 **Qtr:**
Lat: 47.98042 **Long:** -103.66340 **Method:** Interpolation from map
Location Description: This station is located approximately 15 miles N.W. of Alexander North Dakota, in McKenzie county. Left turn onto 39th St NW, 0.15 miles down. Site is on the right.
Submitted By: Bridget Sedlack **Affiliation:**
Address: 3819 Towne Crossing Blvd
City: Mesquite **State:** TX **Zip:** 75150

Received By:

Contact Person: Bridget Sedlack
3819 Towne Crossing, Ste 100
Mesquite, TX 75150

Distance Nearest Occupied Building: **Release Contained:** Yes

Type of Incident: Truck loading pump release

Description of Released Contaminant: Crude Oil

Volume Spilled: 10.00 gallons **Ag Related:** No

EPA Extremely Hazardous Substance: No **Reported to NRC:** Unknown

Cause of Incident:

Alonso stated that he had finished unloading, stopped his pump, and then shut the valve behind the unloading header. He said he then reversed his pump to be able to suck back the oil out of his hose, but he made a mistake and put his pump back into the offloading position, causing it to have pressure in the hose, so when he went to unhook his hose from the unloading header, it sprayed approximately 10 gallons of oil on the ground. Alonso immediately then shut his pump off and used the supplies in his spill kit to soak up any standing oil that was on the ground. There were no water ways affected by the release.

Risk Evaluation:

No immediate risk to air, environment or human health

of Fatalities: 0 **# of Injuries:** 0 **Affected Medium:** 03 - soil

Potential Environmental Impacts:

No impacts to environment. Release was cleaned up.

Action Taken or Planned:

Alonso immediately then shut his pump off and used the supplies in his spill kit to soak up any standing oil that was on the ground. Clean up crew was sent to site, impacted soils were scraped up and temporarily stored on sheeting (and covered) until analytical from composite soil sample comes

back.

Wastes Disposal Location: WISCO Oilfield Special Waste Landfill,
4903 2nd Ave W
Williston, ND 58801
701.572.2135

Agencies Involved:

Updates

Date: 11/7/2014 **Status:** Reviewed - Follow-up Required

Author: Stockdill, Scott

Updated Volume:

Notes:

According to the incident summary, this spill impacted the surrounding area. Followup is necessary.

Date: 11/13/2014 **Status:** Inspection

Author: Martin, Russell

Updated Volume:

Notes:

11/13/2014 at 16:04 on location. No TPG personnel at site; however, there is quite a lot of truck traffic. Called report contact to get exact location of spill due to snow covering site. According to report contact, it was at the "Ironside 19"; however, this does not match any of the locations in the area. No staining visible underneath the snow around site. Talked with one TPG pumper who showed up during inspection; personnel were not aware of event.